


6. Test Setup Photos

Radiated Emission



Conducted Emission




Power supply short-term variation & Power supply variation and failure




Electrostatic Discharge



Conducted radio frequency disturbance



Radiated disturbance



7. External and Internal Photos of the EUT

Reference to the test report No.: CHTEW22040171.

-----End of Report-----