


Report No. : EED32O81096001 Page 36 of 47

## 9 PHOTOGRAPHS OF TEST SETUP

Test model No.:LeRes-S1




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O81096001 Page 37 of 47



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



**Conducted Emissions Test Setup** 









