



COMPANY: TANDY RADIO SHACK			
TITLE: 63-1123 Door Bell Receiver Unit			
DRAWN: YHUANG	DATED: 23 MAY, 02	CODE:	REV: A
CHECKED: ERIC YU	DATED: 23 MAY, 02	SIZE:	
QUALITY CONTROL:	DATED:	DRAWING NO: F06230A	
RELEASED:	DATED:	SCALE:	
SHEET: 2 OF 2			

