



INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission - Dect



Front View




Rear View


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission - Bluetooth



Front View



Rear View

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission - Bluetooth



Front View



Side View 1

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission



Side View 2

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission - Dect



Front View



Side View 1

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission



Side View 2