



F Test Setup Report No.: R1909A0576

RSS-132/-133/-130/-139 Test Setup



Below 1G



Above 1G


Picture 1: Radiated Spurious Emissions Test setup



Report No.: R1909A0576



30MHz-1GHz



1GHz-18GHz

Picture 2: Receiver Spurious Emissions Test setup



Report No.: R1909A0576



Picture 3: AC Power Line Conducted Emissions Test setup