



6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emissions, AC Mains



Photograph 2: Set-up for Radiated Emissions, below 1GHz



Prüfbericht - Nr.: CN22HUFG 001
Test report no.

Seite 14 von 15
Page 14 of 15

Photograph 3: Set-up for Radiated Emissions, above 1GHz

