





## **8 PHOTOGRAPHS OF TEST SETUP**

Test Model No.: S9246LA



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32O81953901 Page 34 of 41

