



B71 20M QPSK 1@99 CH 133372



B71 20M QPSK 100@0 CH 133372



B71 20M 16QAM 1@99 CH 133372



B71 20M 16QAM 100@0 CH 133372




B71 15M QPSK 1@0 CH 133197



B71 15M QPSK 75@0 CH 133197



B71 15M 16QAM 1@0 CH 133197



B71 15M 16QAM 75@0 CH 133197



B71 15M QPSK 1@74 CH 133397



B71 15M QPSK 75@0 CH 133397



B71 15M 16QAM 1@74 CH 133397



B71 15M 16QAM 75@0 CH 133397



B71 10M QPSK 1@0 CH 133172



B71 10M QPSK 50@0 CH 133172



B71 10M 16QAM 1@0 CH 133172




B71 10M 16QAM 50@0 CH 133172



B71 10M QPSK 1@49 CH 133422




B71 10M QPSK 50@0 CH 133422



B71 10M 16QAM 1@49 CH 133422



B71 10M 16QAM 50@0 CH 133422




B71 5M QPSK 1@0 CH 133147



B71 5M QPSK 25@0 CH 133147



B71 5M 16QAM 1@0 CH 133147



B71 5M 16QAM 25@0 CH 133147



B71 5M QPSK 1@24 CH 133447




B71 5M 16QAM 1@24 CH 133447



B71 5M QPSK 25@0 CH 133447



B71 5M 16QAM 25@0 CH 133447



APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

*** End of Report ***

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.
