



6 Photographs of the Test Set-Up

Photograph 1: Set-up for Co-Located Radiated Spurious Emissions, below 1GHz



Photograph 2: Set-up for Co-Located Radiated Spurious Emissions, above 1GHz



Prüfbericht - Nr.: CN22LJYU 002
Test report no.

Seite 25 von 26
Page 25 of 26

Photograph 3: Set-up for Conducted Emissions, AC Mains

