


Report No. :EED32O80248701 Page 30 of 36

10 PHOTOGRAPHS OF EUT Constructional Details

Test model No.: CV301



View of Product-1




View of Product-2









View of Product-3



View of Product-4




















View of Product-5



View of Product-6
























View of Product-7



View of Product-8




























View of Product-10









