



Page 35 of 42 Report No.: EED32O81789301

## 7 PHOTOGRAPHS OF TEST SETUP

Test model No.: CR1



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32O81789301







Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.







































