

APPENDIX 3: Photographs of test setup

Conducted Emission

Cradle: HA-P62IO



Photo 1




Photo 2

UL Japan, Inc.

Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Telephone : +81 478 88 6500

Facsimile : +81 478 82 3373

Conducted Emission

Cradle: HA-P60IO



Photo 1



Photo 2

Radiated Spurious Emission



Photo 1




Photo 2

Worst Case Position
(Horizontal: Z-axis/ Vertical:Y-axis)

X-axis



Y-axis



Z-axis



On Cradle



End of Report