
FCC ID: 2AC76007FIT Report No.: LCS1605191743E

1. INTERIOR PHOTOGRAPHS



Fig.1



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 1 of 5

FCC ID: 2AC76007FIT Report No.: LCS1605191743E




Fig.3



Fig.4

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 2 of 5

FCC ID: 2AC76007FIT Report No.: LCS1605191743E




Fig.5




Fig.6

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 3 of 5

FCC ID: 2AC76007FIT Report No.: LCS1605191743E





Fig.7



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 4 of 5

FCC ID: 2AC76007FIT Report No.: LCS1605191743E




Fig.9

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 5 of 5