


SETUP PHOTOGRAPHS

This document contains 10 photographs


Photograph No.1
Spurious emissions measurement setup in the anechoic chamber with loop antenna



Photograph No.2
Spurious emissions measurement setup in the anechoic chamber
with biconilog antenna




Photograph No.3
Spurious emissions measurement setup in the anechoic chamber with double ridged
guide antenna



Photograph No.4
Spurious emissions measurement setup at the OATS with double ridged guide antenna




Photograph No.5
Conducted spurious emissions measurement setup



Photograph No.6
Radiated unintentional emissions measurement setup in the anechoic chamber
with biconilog antenna




Photograph No.7
Radiated unintentional emissions measurement setup in the anechoic chamber with double ridged guide antenna



Photograph No.8
Radiated unintentional emissions measurement setup in the anechoic chamber



Photograph No.9
Radiated unintentional emissions measurement setup in the anechoic chamber



Photograph No.10
Conducted emissions measurement on AC line setup

