

Annex A: Photographs of the Test Set-up

Photo 1: Radiated Emission





Photo 2: Radiated Emission



2020-12-09 Page 1 of 6



Photo 3: Conducted Emission



2020-12-09 Page 2 of 6

Test report no.: 1-1068/20-06-07



Annex B: External Photographs of the EUT

Photo 1:



Photo 2:



2020-12-09 Page 3 of 6

Test report no.: 1-1068/20-06-07




Annex C: Internal Photographs of the EUT

Photo 1:



Photo 2:




2020-12-09 Page 4 of 6



Photo 3:



Photo 4:



2020-12-09 Page 5 of 6

Test report no.: 1-1068/20-06-07



Photo 5:



2020-12-09 Page 6 of 6