





8 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)















Page 46 of 57 Report No.: EED32P81158901



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



Conducted Emissions Test Setup









