









Report No.: EED32L00189801

PHOTOGRAPHS OF TEST SETUP

Test model No.: WCT0SR2311



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)




















Report No.: EED32L00189801



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz)
There are absorbing materials under the ground.



















Report No.: EED32L00189801



























































