


Report No. : EED32N81433503 Page 29 of 35

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: SE65DP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)







Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

