


Project No.: 23081702-03

Set-Up for Conducted Emission Test





Lab: Hwa-Hsing (Dongguan) Testing Co., Ltd.

Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic
of China

Tel: <u>0769-83078199</u>
Web.: <u>www.hwa-hsing.com</u>
E-Mail: <u>customerservice.dg@hwa-hsing.com</u>



Project No.: 23081702-03

Set-Up for Radiated Emission Test








Lab: Hwa-Hsing (Dongguan) Testing Co., Ltd.


Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic
of China

Tel: <u>0769-83078199</u>
Web.: <u>www.hwa-hsing.com</u>
E-Mail: <u>customerservice.dg@hwa-hsing.com</u>



Project No.: 23081702-03





-End-

Lab: Hwa-Hsing (Dongquan) Testing Co., Ltd.

Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongquan City, People's Republic
of China

Tel: 0769-83078199
Web.: www.hwa-hsing.com
E-Mail: customerservice.dg@hwa-hsing.com

Release Ver. 1.5