




Report No. : EED32M80160303 Page 63 of 65

9 PHOTOGRAPHS OF TEST SETUP





Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)

Hotline: 400-6788-333 www.cti-cert.com E-mail: info@cti-cert.com Complaint call: 0755-33681700 Complaint E-mail: complaint@cti-cert.com



Report No.: EED32M80160303









Conducted Emissions Test Setup









