

3.9 Radiated and Line-Conducted Emission Configuration Photographs




Figure 3.9 - 1: Worst Case Radiated Emission, Front View




Figure 3.9 - 2: Worst Case Radiated Emission, Rear View

This page intentionally left blank

Figure 3.9 - 3: Worst Case Line-Conducted Emission, Front View

This page intentionally left blank

Figure 3.9 - 4: Worst Case Line-Conducted Emission, Rear View

Test Date: April 24, 2001
UST Project: 01-0137
Customer: Axonn L.L.C.
Model: AX-550 Transmitter

Photograph(s) for Spurious Emissions (Front)

Test Date: April 24, 2001
UST Project: 01-0137
Customer: Axonn L.L.C.
Model: AX-550 Transmitter

Photograph(s) for Spurious Emissions (Back)

