


Page 6 / 28 **Report No.:** T191125N07

Rev. 00


Internal Photo (Model: SC6000 PRIME)







Page 7 / 28 **Report No.:** T191125N07 Rev. 00








 Report No.:
 T191125N07
 Page
 8 / 28


 Rev.
 00









Page 9 / 28 **Report No.:** T191125N07 Rev. 00







Page 10 / 28 **Report No.:** T191125N07 Rev. 00









Page 11 / 28


Report No.: T191125N07 Rev. 00









Page 12 / 28 **Report No.:** T191125N07 Rev. 00









Page 13 / 28 **Report No.:** T191125N07 Rev. 00








Page 14 / 28 **Report No.:** T191125N07 Rev. 00









Page 15 / 28 **Report No.:** T191125N07 Rev. 00








Page 16 / 28 **Report No.:** T191125N07 Rev. 00





Page 17 / 28 **Report No.:** T191125N07

Rev. 00







Page 18 / 28 **Report No.:** T191125N07 Rev. 00







Page 19 / 28

Report No.: T191125N07 Rev. 00








Report No.: T191125N07

Page 20 / 28 Rev. 00








Page 21 / 28

Report No.: T191125N07 Rev. 00









 Report No.:
 T191125N07
 Page
 22 / 28

 Rev.
 00








Page 23 / 28 **Report No.:** T191125N07 Rev. 00







Page 24 / 28 **Report No.:** T191125N07 Rev. 00








Page 25 / 28 **Report No.:** T191125N07 Rev. 00









Page 26 / 28 **Report No.:** T191125N07 Rev. 00








Page 27 / 28 **Report No.:** T191125N07 Rev. 00







Page 28 / 28

Report No.: T191125N07 Rev. 00

