





*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -3.71 dBm
SWT 5 ms 2.410400000 GHz



Comment A: RF conducted spurious at low channel
ATT-3dB CL-1dB
Date: 7.AUG.2002 16:01:49



Comment A: RF conducted spurious at low channel

ATT=3dB CL=1dB

Date: 7.AUG.2002 16:06:11




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -58.68 dBm
SWT 760 ms 2.513566000 GHz

Ref -10 dBm

*Att: 10 dB

1 PK
MARKER



Start 2.4835 GHz

751.65 MHz/

Stop 10 GHz

Comment A: RF conducted spurious at low channel
ATT=3dB CL=1dB
Date: 7.AUG.2002 16:08:17




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -57.61 dBm
SWT 1.5 s 24.91000000 GHz

Ref -10 dBm

*Att. 10 dB

1 PK
MAXH



Start 10 GHz

1.5 GHz/

Stop 25 GHz

Comment A: RF conducted spurious at low channel
ATT-3dB CL-1dB

Date: 7.AUG.2002 16:09:56




*RBW 100 kHz Marker 1 {T1 }
VBW 300 kHz -3.16 dBm
SWT 5 ms 2.435400000 GHz

Ref 10 dBm

*Att 20 dB

SWT 5 ms

2.435400000 GHz



Comment A: RF conducted spurious at middle channel(
ATT=3dB CL=1dB

Date: 7.AUG.2002 16:11:56



*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -51.64 dBm
*Att 10 dB
SWT 240 ms 698.340000000 MHz


Ref 0 dBm

*Att 10 dB

SWT 240 ms

698.340000000 MHz

1 PK
MAXH



Start 30 MHz

231 MHz/

Stop 2.4 GHz

Comment A: RF conducted spurious at middle channel
ATT=3dB CL=1dB

Date: 7.AUG.2002 16:13:31




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz
SWT 760 ms

Ref 0 dBm

*Att 10 dB

2.543632000 GHz

1 PK
MAXH



Comment A: RF conducted spurious at middle channel{

ATT=3dB CL=1dB

Date: 7.AUG.2002 16:15:00




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -57.71 dBm
SWT 1.5 s 24.520000000 GHz

Ref 0 dBm

*Att 10 dB

1 PK
MARK



Start 10 GHz

1.5 GHz/


Stop 25 GHz

Comment A: RF conducted spurious at middle channel{
ATT=3dB CL=1dB

Date: 7.AUG.2002 16:16:02



*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -3.51 dBm
SWT 5 ms 2.460400000 GHz



Comment A: RF conducted spurious at high channel
ATT=3dB CL=1dB
Date: 7.AUG.2002 16:18:25




*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -52.73 dBm
SWT 240 ms 722.040000000 MHz

Ref 0 dBm

*Att 10 dB

1 PK
MAX



Comment A: RF conducted spurious at high channel

ATT-3dB CL-1dB

Date: 7.AUG.2002 16:19:52




*RBW 100 kHz Marker 1 [T1]
VEW 300 kHz -54.63 dBm
SWT 760 ms 2.483500000 GHz

Ref 0 dBm

*Att 10 dB

1 PK
MAXH



Start 2.4835 GHz

751.65 MHz/

Stop 10 GHz


Comment A: RE conducted spurious at high channel

ATT=3dB CL=1dB

Date: 7.AUG.2002 16:21:06



*RBW 100 kHz Marker 1 [T1]
VBW 300 kHz -57.64 dBm
SWT 1.5 s 24.820000000 GHz



Comment A: RF conducted spurious at high channel
ATT=3dB CL=1dB
Date: 7.AUG.2002 16:22:59