



INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission – Baby Unit, Charging and DECT Transmission On



Front View




Rear View

The EUT is placed at the center of turntable


INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission – Baby Unit, Charging and DECT Transmission On (with Light On and playing melody)



Front View




Side View 1

Test Report Number: 22061224HKG-001
FCC ID: EW780-2714-00
IC: 1135B-80271400

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

AC Conducted Emission – Baby Unit, Charging and DECT Transmission On (with Light On and playing melody)



Side View 2