


Report No. : EED32P81691801





## 9 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1 (Below 1GHz)



Radiated spurious emission Test Setup-2 (Above 1GHz)






Report No. : EED32P81691801





Page 34 of 40



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

