


Annex A


Undesirable Emissions Conducted



High ch_1 -26.5 GHz




High ch_26.5 - 40 GHz






High ch_2nd harmonic




High ch_30 - 1000 MHz






Low ch_1 - 26.5 GHz




Low ch_26.5 - 40 GHz






Low ch_2nd harmonic




Low ch_30- 1000 MHz






Mid ch_1 - 26.5 GHz




Mid ch_26.5 - 40 GHz






Mid ch_2nd harmonic




Mid ch_3.85 GHz



*Note the 3.8 GHz spur was measured radiated. Please see Annex B for outcome.




Mid ch_30 - 1000 MHz





A Mode Mask



N Mode Mask

