# **The Worst Case Configuration Photographs**



Figure 1 – Front with 0mm Separation




Figure 2 – Back with 0mm Separation

# **The Worst Case Configuration Photographs**



Figure 3 – Right with 0mm Separation



Figure 4 – Top with 0mm Separation

# The Worst Case Configuration Photographs



Figure 5 – Front with 0mm Separation (antenna extended)



Figure 6 – Back with 0mm Separation (antenna extended)

# The Worst Case Configuration Photographs



Figure 7 – Right with 0mm Separation (antenna extended)



Figure 8 – Top with 0mm Separation (antenna extended)