




9 PHOTOGRAPHS OF TEST SETUP

Test model No.:CV 298



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32O80248901





Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

