



Page 1 of 8 Report No.: 8226EU012201W-AC

ANNEX C INTERNAL PHOTOS

(Model No.: H6147)


PHOTO 1








Page 2 of 8 Report No.: 8226EU012201W-AC









Page 3 of 8 Report No.: 8226EU012201W-AC

(Model No.: H6125)


PHOTO 5








Page 4 of 8 Report No.: 8226EU012201W-AC









Page 5 of 8 Report No.: 8226EU012201W-AC


(Model No.: H6126)








Page 6 of 8 Report No.: 8226EU012201W-AC









Page 7 of 8 Report No.: 8226EU012201W-AC

(Model No.: H7090)


PHOTO 13








Page 8 of 8 Report No.: 8226EU012201W-AC





--- End ---