

May 28, 2002

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
USA

**Subject: FCC ID: NTAXMETER2 - clarifications**

Gentlemen,

Following your request we provide additional clarification regarding Low Power Transceiver NTAXMETER2:

The actual installation of the unit is always inside and at the bottom of the metal pit buried in the ground with unlimited width, so the test configuration is absolutely the worst-case scenario compared to the actual installation.

Sincerely yours



Roman Sternberg  
VP Marketing