



SAR **Dipole Performance Measurement** Report

EUT Type: SAR Validation Dipole and Waveguide

DIP 0G835-332

DIP 1G800-329 **Model Name:** DIP 1G900-333

DIP 2G450-335

SATIMO Brand Name:

Test Conclusion: Pass

Test Date: 27 Jun. 2019

Date of Issue: 28 Jun. 2019

Arana Bu **Testing Engineer**

(Aaron Bu)

Technical Manager

Authorized Signatory:

(Vita Li)

Any reproduction of this document must be done in full. No single part of this document may be reproduced without permission from STS, All Test Data Presented in this report is only applicable to presented Test sample.



1. Equipment List

| Kind of Equipment | Manufacturer | Type No. | Serial No. | Last Calibration | Calibrated Until |
|----------------------|--------------|---------------------|--------------------|------------------|------------------|
| PC | Acer | N/A | N/A | N/A | N/A |
| E-Field Probe | MVG | SSE5 | SN 14/16 EP309 | 2017.12.15 | 2018.12.14 |
| Dielectric Probe Kit | MVG | SCLMP | SN 32/14 OCPG67 | 2017.12.03 | 2018.12.02 |
| Phantom1 | MVG | SAM | SN 32/14 SAM115 | N/A | N/A |
| Phantom2 | MVG | SAM | SN 32/14 SAM116 | N/A | N/A |
| Attenuator | Agilent | 99899 | DC-18GHz | N/A | N/A |
| Directional coupler | Narda | 4226-20 | 3305 | N/A | N/A |
| Network Analyzer | Agilent | 8753ES | US38432810 | 2018.03.08 | 2019.03.07 |
| Multi Meter | Keithley | Multi Meter 2000 | 4050073 | 2017.10.15 | 2018.10.14 |
| Signal Generator | Agilent | N5182A | MY50140530 | 2017.10.15 | 2018.10.14 |
| Power Amplifier | DESAY | ZHL-42W | 9638 | 2017.10.15 | 2018.10.14 |
| Power Meter | R&S | NRP | 100510 | 2017.10.15 | 2018.10.14 |
| Power Sensor | R&S | NRP-Z11 | 101919 | 2017.10.15 | 2018.10.14 |
| Power Sensor | Agilent | E9301A | MY41497725 | 2017.10.15 | 2018.10.14 |
| hygrothermograph | MiEO | HH660 | N/A | 2017.10.18 | 2018.10.17 |



2.<Justification of the extended calibration>


Referring to KDB 865664 D01, if dipoles are verified in return loss<-20dB, (within 20% of prior calibration), and in impedance (within 5 ohm of prior calibration), the annual calibration is not necessary and the calibration interval can be extended.

| Head 835 MHz | | | | |
|---------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -28.11 | - | 51.6 | - |
| 2018.08.15 | -27.05 | -3.77 | 54.69 | 3.09 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Head 835MHz






| Body 835 MHz | | | | |
|---------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -23.87 | - | 49.0 | - |
| 2018.08.15 | -22.21 | -6.95 | 52.59 | 3.59 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Body 835MHz






| Head 1800 MHz | | | | |
|---------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -29.51 | - | 46.7 | - |
| 2018.08.16 | -25.32 | -14.2 | 45.24 | -1.46 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Head 1800 MHz






| Body 1800 MHz | | | | |
|------------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -24.59 | - | 48.8 | - |
| 2018.08.16 | -24.95 | 1.46 | 45.42 | -3.38 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Body 1800 MHz






| Head 1900 MHz | | | | |
|------------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -23.68 | - | 51.2 | - |
| 2018.08.16 | -25.00 | 5.57 | 47.12 | -4.08 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Head 1900 MHz




| Body 1900 MHz | | | | |
|------------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -20.22 | - | 48.8 | - |
| 2018.08.16 | -23.26 | 15.03 | 47.11 | -1.79 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Body 1900 MHz






| Head 2450 MHz | | | | |
|------------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -26.00 | - | 46.1 | - |
| 2018.08.16 | -29.56 | 13.69 | 47.53 | 1.43 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Head 2450 MHz





| Body 2450 MHz | | | | |
|---------------------|---------------------|-----------|-----------|------------|
| Date of Measurement | Return Loss (dB) | Delta (%) | Impedance | Delta(ohm) |
| 2017.08.15 | -32.75 | - | 48.8 | - |
| 2018.08.16 | -31.06 | -5.16 | 45.61 | -3.19 |

The return loss is <-20dB, within 20% of prior calibration; the impedance is within 5 ohm of prior calibration. Therefore the verification result should support extended calibration.

<Dipole Verification Data>

Body 2450 MHz

