


APPENDIX 3: Photographs of test setup

Radiated Emission

Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



Associated equipment



Antenna terminal conducted tests



Photo 1




Photo 2



Photo 3



Photo 4

Frequency Stability (Temperature)




Photo 1




Photo 2

End of Report