

Report No.: EED32O81949201 Page 34 of 42

## **8 PHOTOGRAPHS OF TEST SETUP**

Test Model No.: S9246AC




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)

Report No.: EED32O81949201 Page 35 of 42



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.