


7. Photographs of the Test Set-Up


Photograph 1: Set-up for Spurious Emissions (Front View 1)




Photograph 2: Set-up for Spurious Emissions (Front View 2)




Photograph 3: Set-up for Spurious Emissions (Back View 1)




Photograph 4: Set-up for Spurious Emissions (Back View 2)



Photograph 5: Set-up for Spurious Emissions (Back View 3)



Photograph 6: Set-up for Spurious Emissions (Back View 4)




Photograph 7: Set-up for Conducted testing



Prüfbericht - Nr.: 50254142 001
Test Report No.

Seite 39 von 41
Page 39 of 41

Photograph 8: Set-up for Conducted testing



Photograph 9: Set-up for Mains Conducted testing (Back View)



Prüfbericht - Nr.: 50254142 001
Test Report No.

Seite 40 von 41
Page 40 of 41

Photograph 10: Set-up for Mains Conducted testing (Front View)

