



Project No.: 2411180519-02-03

## **Set-Up for Conducted Emission Test**





Lab: Hwa-Hsing (Dongguan) Testing Co., Ltd.


Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic of China


Tel: 0769-85598986 Web.: www.lyns-tci.com E-Mail: service-hs@lyns-tci.com



Project No.: 2411180519-02-03

## **Set-Up for Radiated Emission Test**







Lab: Hwa-Hsing (Dongguan) Testing Co., Ltd.

Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic of China


Tel: <u>0769-85598986</u> Web.: www.lyns-tci.com
E-Mail: service-hs@lyns-tci.com

Release Ver. 1.5



Project No.: 2411180519-02-03





-End-

Lab: <u>Hwa-Hsing (Dongguan) Testing Co., Ltd.</u>

Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic of China

Tel: 0769-85598986 Web.: www.lyns-tci.com E-Mail: service-hs@lyns-tci.com

Release Ver. 1.5