

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission


Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)



Pre-Check Worst Case Position


EUT
0 deg.




Antenna *1)
-90 deg.



30 deg.



0 deg.



90 deg.



*1) The Above position of Antenna is for when Car Navigation at 0 deg.
The position of Antenna is linked to the position of Car Navigation.

Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report