



Report No. : EED32N80836801 Page 44 of 76

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: HD6-600W



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32N80836801 Page 45 of 76



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

