




B38 5M 16QAM 1@0 CH 37775




B38 5M 16QAM 25@0 CH 37775




B38 5M QPSK 1@24 CH 38225




B38 5M QPSK 25@0 CH 38225




B38 5M 16QAM 1@24 CH 38225




B38 5M 16QAM 25@0 CH 38225




B38 20M 64QAM 1@0 CH 37850




B38 20M 64QAM 100@0 CH 37850




B38 20M 64QAM 1@99 CH 38150




B38 20M 64QAM 100@0 CH 38150




B38 15M 64QAM 1@0 CH 37825




B38 15M 64QAM 75@0 CH 37825




B38 15M 64QAM 1@74 CH 38175




B38 15M 64QAM 75@0 CH 38175




B38 10M 64QAM 1@0 CH 37800




B38 10M 64QAM 50@0 CH 37800




B38 10M 64QAM 1@49 CH 38200




B38 10M 64QAM 50@0 CH 38200




B38 5M 64QAM 1@0 CH 37775




B38 5M 64QAM 25@0 CH 37775



B38 5M 64QAM 1@24 CH 38225



B38 5M 64QAM 25@0 CH 38225



## APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

## APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

\*\*\* End of Report \*\*\*

---

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.

---