


Report No. : EED32N80491501 Page 42 of 54

9 PHOTOGRAPHS OF TEST SETUP

Test model No.: RM110



Radiated spurious emission Test Setup-1(Below 1GHz)




Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32N80491501 Page 43 of 54



Conducted emission Test Setup



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.









