


### **APPENDIX 3: Photographs of test setup**

#### **Conducted Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**


**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

### **Radiated Spurious Emission**




**Photo 1**




**Photo 2**

**Worst Case Position (Horizontal: X-axis/ Vertical:X-axis)**


**X-axis**



**Y-axis**



**Z-axis**



**End of Report**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124