



Report No.: EED32Q80655102



## **6 PHOTOGRAPHS OF TEST SETUP**



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz)Close up photo















Report No.: EED32Q80655102







Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 18GHz)















Report No.: EED32Q80655102







Radiated spurious emission Test Setup-5(Above 1GHz)
There are absorbing materials under the ground.













































