




B66\_10M\_64QAM\_1@0\_CH\_132022




B66\_10M\_64QAM\_50@0\_CH\_132022




B66\_10M\_64QAM\_1@49\_CH\_132622




B66\_10M\_64QAM\_50@0\_CH\_132622




B66\_5M\_64QAM\_1@0\_CH\_131997




B66\_5M\_64QAM\_25@0\_CH\_131997




B66\_5M\_64QAM\_1@24\_CH\_132647




B66\_5M\_64QAM\_25@0\_CH\_132647



B66\_3M\_64QAM\_1@0\_CH\_131987




B66\_3M\_64QAM\_15@0\_CH\_131987




B66\_3M\_64QAM\_1@14\_CH\_132657




B66\_3M\_64QAM\_15@0\_CH\_132657




B66\_1.4M\_64QAM\_1@0\_CH\_131979




B66\_1.4M\_64QAM\_6@0\_CH\_131979



B66\_1.4M\_64QAM\_1@5\_CH\_132665



B66\_1.4M\_64QAM\_6@0\_CH\_132665



## APPENDIX 1 PHOTOS OF TEST SETUP

See test photos attached in Appendix 1 for the actual connections between Product and support equipment.

## APPENDIX 2 PHOTOS OF EUT CONSTRUCTIONAL DETAILS

Refer to Appendix 2 for EUT external and internal photos.

\*\*\* End of Report \*\*\*

---

The test report is effective only with both signature and specialized stamp. The result(s) shown in this report refer only to the sample(s) tested. Without written approval of UnionTrust, this report can't be reproduced except in full.

---