


Report No.: EED32P80965001 Page 37 of 49

8 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32P80965001 Page 38 of 49



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission









