


## ANNEX C INTERNAL PHOTOS




136117\_11.JPG: ODIN-W160, top view with shielding

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F145298E9

 Date of issue:
 19 June 2015
 Order No.:
 14-115298
 page 1 of 3



## ANNEX C INTERNAL PHOTOS




136117\_13.JPG: ODIN-W160, top view, shielding removed

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F145298E9

 Date of issue:
 19 June 2015
 Order No.:
 14-115298
 page 2 of 3



## ANNEX C INTERNAL PHOTOS



136117\_12.JPG: ODIN-W160, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F145298E9

 Date of issue:
 19 June 2015
 Order No.:
 14-115298
 page 3 of 3