APPENDIX E: PHOTOGRAPHS OF THE TEST SET-UP



Report No.: WT218002348 Page 1 of 7

Photo 1: Measurement DASY6




Photo 3: Left Tilt 0mm




Photo 4: Right Cheek 0mm



Photo 5: Right Tilt 0mm



Photo 6: Front Side 15mm

Photo 2: Left Cheek 0mm

Report No.: WT218002348 Page 2 of 7



Photo 7: Back Side 15mm



Photo 8: Front Side 10mm



Photo 9: Back Side 10mm




Photo 10: Left Side 10mm





Report No.: WT218002348 Page 3 of 7

Photo 11: Right Side 10mm



Photo 13: Bottom Side 10mm





Photo 15: Top Side 17mm





Photo 14: Back Side 17mm



N/A

Report No.: WT218002348 Page 4 of 7



N/A

Report No.: WT218002348 Page 5 of 7

Photograph: Liquid depth

Photo 18: Head 750 Depth (15.0cm)




Photo 20: Head 1900 Depth (15.0cm)




Photo 22: Head 1750 Depth (15.0cm)

Photo 19: Head 835 Depth (15.0cm)





Photo 21: Head 2450 Depth (15.0cm)



Photo 23: Head 2600 Depth (15.0cm)

Report No.: WT218002348 Page 6 of 7



Report No.: WT218002348 Page 7 of 7