Report No.: CR240106788-00B-TSP

TEST SETUP PHOTOGRAPHS


Conducted Emissions Front View




Conducted Emissions Side View




Page 1 of 4






Page 2 of 4







Page 3 of 4



