


Photographs –Model iris 708 Test Setup

Photograph – Conducted Emission Test Setup at Test Site 1#




Photograph – Radiation Spurious Emission Test Setup

Below 30MHz




30-1000MHz



Above 1GHz



Photograph – Extreme Condition Test Setup



Photograph –2G&3G Conducted Test Setup

