

INTERNAL PHOTOGRAPHS

This document contains 5 photographs

Photograph No.1
PowerG beam detector PG9200AX internal view




Photograph No.2
PG9200AX Transmitter Back Box front view



Photograph No.3
PG9200AX Receiver Back Box front view



Photograph No.4
PG9200AX detector RF card front view



Photograph No.5
PG9200AX detector RF card rear side view

