

Annex B

Photographs of EUT

part of / in addition to

Test report no.: 24060222-41089-0


Table of contents

1. EUT and AE photographs.....	3
--------------------------------	---

Annex B of TR no.: 24060222-41089-0

1. EUT and AE photographs

Photograph 1: View 1, EUT A, external photograph




Photograph 2: View 2, EUT A, external photograph



Annex B of TR no.: **24060222-41089-0**

Photograph 3: View 1, EUT A, internal photograph




Photograph 4: View 2, EUT A, internal photograph



Annex B of TR no.: 24060222-41089-0

Photograph 5: AE 1



intellion | LotTrack CertificationClient

IP address: 192.168.200.12 disconnect SN: 24246P0012

Test device selection

Model: Controller G4, Type NA Device ID (I): not connected

RF Testing

Carrier duration: 30 [sec, 1 - 255]
 No. of iterations: 1 [1 - 255]
 Frequency: 919800 [kHz, 919200 - 920800]
 Modulation: ☒ Modulated
 Antenna: Antenna1 (All antenna ports)
 TX power: 0 [dBm, -30 - 14]
Start: Send carrier

Device Testing

Test duration: 30 [sec, 1 - 255]
 No. of iterations: 1 [1 - 255]
Start: KeepAlive test

Current communication result: -
 Device is running since: -
 Last successful communication: -


Controller: 192.168.200.12, connected Status: Idle

Photograph 6: AE 2



Annex B of TR no.: **24060222-41089-0**

Photograph 7: AE 3




Photograph 8: AE 4



Annex B of TR no.: **24060222-41089-0**

Photograph 9: AE 5




Photograph 10: AE 6



Annex B of TR no.: **24060222-41089-0**


Photograph 11: AE 7



5. Conducted emissions measurements



Photograph 9: Overall view, set-up 1.



Photograph 10: Overall view, set-up 2.