


Project No.: 24032713-02-03

Set-Up for Conducted Emission Test





Lab: Hwa-Hsing (Dongguan) Testing Co., Ltd.

Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic
of China

Web.: www.hwa-hsing.com
E-Mail: customerservice.dg@hwa-hsing.com

Tel: <u>0769-83078199</u>

Release Ver. 1.5



Project No.: 24032713-02-03

Set-Up for Radiated Emission Test





Lab: Hwa-Hsing (Dongguan) Testing Co., Ltd.

Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic


of China


Tel: <u>0769-83078199</u> Web.: www.hwa-hsing.com
E-Mail: customerservice.dg@hwa-hsing.com

Release Ver. 1.5



Project No.: 24032713-02-03





-End-

Lab: Hwa-Hsing (Dongguan) Testing Co., Ltd.

Address: No. 101, Building N1, Yuyuan 2 Road, Yuyuan Industrial
Park, HuangJiang Town, Dongguan City, People's Republic

Web.: www.hwa-hsing.com
E-Mail: customerservice.dg@hwa-hsing.com of China

Tel: <u>0769-83078199</u>

Release Ver. 1.5